

# Oil Field Environmental Incident Summary

**Incident:** 20150305093812      **Date/Time of Notice:** 03/05/2015 09:38

**Responsible Party:** XTO ENERGY INC.

**Well Operator:** XTO ENERGY INC.

**Well Name:** CHARLSON 44-32H

**Field Name:** CHARLSON

**Well File #:** 17162

**Date Incident:** 3/4/2015      **Time Incident:** 10:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 154

**Rng:** 95

**Sec:** 32

**Qtr:**

**Location Description:**

**Submitted By:** Shawn Dahl

**Received By:**

**Contact Person:** Shawn Dahl  
2732 Hwy 85 N  
Alexander, MT 58831

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Barrels	3	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none.

**Areal Extent:**

**Potential Environmental Impacts:**

none.

**Action Taken or Planned:**

The spill was contained in an earthen berm. the free standing liquids were sucked up and taken to a disposal facility, and the impacted gravel was removed and taken to an approved disposal facility. The 1" suction valve that was open was closed to stop the incident.

**Wastes Disposal Location:** The impacted material will be hauled to Secure liquid and solids disposal.

**Agencies Involved:**

**Updates**

**Date:** 3/5/2015      **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.